

Monday, 14 February 2022

Te Hui o Te Kaunihera ā-Rohe o Heretaunga

Hastings District Council

Hastings District Rural Community Board Meeting

Kaupapataka

Open Attachment (2) Under Separate Cover

Te Rā Hui:
Meeting date: **Monday, 14 February 2022**

Te Wā:
Time: **2.00pm**

Te Wāhi:
Venue: **Council Chamber
Ground Floor
Civic Administration Building
Lyndon Road East
Hastings**

**Watch Council meetings
streamed live on our website
www.hastingsdc.govt.nz**

HASTINGS DISTRICT COUNCIL
207 Lyndon Road East, Hastings 4122 | Private Bag 9002, Hastings 4156
Phone **06 871 5000** | www.hastingsdc.govt.nz
TE KAUNIHERA Ā-ROHE O HERETAUNGA

ITEM	SUBJECT	PAGE
	RURAL COMMUNITY BOARD MEETING 14 FEBRUARY 2022 - SEPARATE ATTACHMENTS TO AGENDA ITEMS 4 AND 7	
Attachment 2:	Agenda Item 7 - RCB Works Update Photos - November 2021 to February 2022	3

February 2022 RCB Photos

Aropaoanui Rd: Manhole replacement	Aropaoanui Rd: Manhole replacement
	
Aropaoanui Rd: Slip clearing	Aropaoanui Rd: Slip clearing
	

February 2022 RCB Photos

<p>Berry Rd: build up shoulder</p> 	<p>Berry Rd: Bridge Maintenance</p> 
<p>Corbin Rd: Culvert extension</p> 	<p>Corbin Rd: Headwall</p> 

February 2022 RCB Photos

<p>Dartmoor Rd: Sign installation</p> 	<p>Dampney Bridge: Annual Maintenance</p> 
<p>Darkys Spur Rd: Bridge deck repairs</p> 	<p>Darkys Spur Rd: Bridge deck repairs</p> 
<p>Dartmoor Rd: Fallen Tree Call out</p> 	<p>Darkys Spur Rd: Sign installation</p> 

Item 7

February 2022 RCB Photos

Glengarry Rd: Scour repair	Glengarry Rd: Scour repair
	
Hendley Rd: Watertables	Hendley Rd: Watertables
	
Hendley Rd: Watertables	Hendley Rd: Watertables
	

Item 7

February 2022 RCB Photos

Hendley Rd: Watertable Maintenance	Hendley Rd: Watertable Maintenance
	
Huiarangi Rd: Watertables	Huiarangi Rd: Watertables
	
Kaihika Bridge: Annual maintenance	Parahau Bridge: Annual maintenance
	

Item 7

February 2022 RCB Photos

Kereru Rd: Slip Removal	Kereru Rd: Slip Removal
	
Bridge Pa: Limesand Footpaths	Bridge Pa: Limesand Footpaths
	
McDonalds Culvert Bridge: Annual Bridge Inspections	Mutiny Bridge: Annual Bridge Inspections
	

February 2022 RCB Photos

Maraekakaho Rd: Sight rail	Maraekakaho Rd: Sight rail
	
Maraekakaho Rd: Footpaths	Maraekakaho Rd: Footpaths
	

Item 7

February 2022 RCB Photos

McVicar Culvert Bridge: Annual Maintenance	McIntyre's Access Rd: Sign installation
	
Mangatutu Low Level Bridge: Annual Maintenance	Middle Rd: Sign installation
	
Matahorua Rd: Scour Repair	Matahorua Rd: Scour Repair
	

Item 7

February 2022 RCB Photos

<p>Matapiro Rd: Reseals</p> 	<p>Matapiro Rd: Reseals</p> 
<p>Mokamoka Rd: Flushing</p> 	<p>Mokamoka Rd: Watertable and headwall</p> 

February 2022 RCB Photos

<p>Maraekakaho Rd: Litter</p> 	<p>Matahorua Rd: Fallen Tree</p> 
<p>Maraetotara Rd/Okaihau Rd: Grass weed wacking</p> 	<p>Ngatarawa Rd: Litter</p> 
<p>Ngatarawa Rd: Digouts & Stabilising</p> 	<p>Ngatarawa Rd: Digouts & Stabilising</p> 

Item 7

February 2022 RCB Photos

Otamauri Rd: Watertable Maintenance	Otamauri Rd: Watertable Maintenance
	
Ocean Beach Rd: Sight rails	Ocean Beach: Signs
	

February 2022 RCB Photos

<p>Pohokura Rd: Headwall</p>	<p>Puketapu Rd: Litter removal</p>
	
<p>Pakaututu Rd: Scour repair</p>	<p>Pakaututu Rd: Scour repair</p>
	

February 2022 RCB Photos

<p>Rissington bridge: Over height warning signage</p> 	<p>Rissington bridge: Over height warning signage</p> 
<p>Puketitiri Rd: Vegetation clearing</p> 	<p>Puketitiri Rd: Vegetation clearing</p> 

Item 7

February 2022 RCB Photos

Puketitiri Rd: Bridge Maintenance	Puketitiri Rd: Bridge Maintenance
	
Poporangi Bridge: Annual Maintenance	Sentry Box Bridge: Annual Maintenance
	

Item 7

February 2022 RCB Photos

<p>Rissington Bridge: signs installation</p> 	<p>Rissington Bridge: signs installation</p> 
<p>Springfield Rd: Sign installation</p> 	<p>Nestors Culvert Bridge: Annual Bridge Maintenance</p> 

February 2022 RCB Photos

Nestors Culvert Bridge: Annual Bridge Maintenance	Taheke Bridge: Annual Bridge Maintenance
	
Taihape Rd: Lime pathways	Taihape Rd: Lime pathways
	
Taihape Rd: Lime pathways	Taihape Rd: Lime pathways
	

Item 7

February 2022 RCB Photos

<p>Taihape Rd: Bridge Maintenance</p> 	<p>Taihape Rd: Bridge Maintenance</p> 
<p>Taheke Bridge: Annual Bridge Maintenance</p> 	<p>Tawa Rd / Waipoapoa Rd: Grass weed wacking</p> 
<p>Vicarage Rd: Litter</p> 	<p>Waimarama Rd: Signs</p> 

February 2022 RCB Photos

Waimarama Rd: Dumpsite demolition	Waimarama Rd: Dumpsite demolition
	
Waimarama Rd: Sign cleaning	Waimarama Rd: Sign cleaning
	
Waikoau Rd: Watertabling	Waikoau Rd: Watertabling
	

Item 7