

Monday, 16 September 2024

Te Hui o Te Kaunihera ā-Rohe o Heretaunga

Hastings District Council

Hastings District Rural Community Board Meeting

Kaupapataka

Attachment Vol 2

Te Rā Hui:
Meeting date: **Monday, 16 September 2024**

Te Wā:
Time: **2.00pm**

Te Wāhi:
Venue: **Council Chamber
Ground Floor
Civic Administration Building
Lyndon Road East
Hastings**

**Watch Council meetings
streamed live on our website
www.hastingsdc.govt.nz**

HASTINGS DISTRICT COUNCIL
207 Lyndon Road East, Hastings 4122 | Private Bag 9002, Hastings 4156
Phone **06 871 5000** | www.hastingsdc.govt.nz
TE KAUNIHERA Ā-ROHE O HERETAUNGA

ITEM	SUBJECT	PAGE
6.	RURAL TRANSPORTATION ACTIVITY REPORT	
	Attachment 1: Transport - Roads General (See notes) - Rural Community Board Photos - June 2024 to August 2024	3

Rural Community Board – September 2024 Photos, June-August

Apley Rd: Fallen Tree Removal		Apley Rd: Fallen Tree Removal	
			
Aropaoanui Rd: Aropaoanui Low Level Bridge: Debris Removal		Aropaoanui Rd: Aropaoanui Low Level Bridge: Debris Removal	
			
Aropaoanui Rd: Slips Clearing		Aropaoanui Rd: Slips Clearing	
			

Item 6

Rural Community Board – September 2024 Photos, June-August

Aropaoanui Rd: Aropaoanui Low Level Bridge: Deck Repair



Aropaoanui Rd: Aropaoanui Low Level Bridge: Deck Repair



Aropaoanui Rd: Safety Netting Installation



Aropaoanui Rd: Bollard Installation



Big Hill Rd: Tree Removal



Big Hill Rd: Tree Removal



Rural Community Board – September 2024 Photos, June-August

Big Hill Rd: Sight Rail Installation



Big Hill Rd: Sight Rail Installation



Crownthorpe Rd: Crownthorpe Bridge: Drain Plate Installation



Crownthorpe Rd: Crownthorpe Bridge: Drain Plate Installation



Crystall Rd: Detritus Collection



Crystall Rd: Pole Replacement



Rural Community Board – September 2024 Photos, June-August

<p>Crystall Rd: Sign Installation</p> 	<p>Crystall Rd: Sign Installation</p> 
<p>Crystall Rd: Detritus Removal</p> 	<p>Crystall Rd: Detritus Removal</p> 
<p>Crownthorpe Settlement Rd: Redundant Sign Removal</p> 	<p>Crownthorpe Settlement Rd: Redundant Sign Removal</p> 

Rural Community Board – September 2024 Photos, June-August




Darkys Spur Rd: Scour Repair	Darkys Spur Rd: Scour Repair
	
Darkys Spur Rd: Slip & Tree Removal	Darkys Spur Rd: Slip & Tree Removal
	
Darkys Spur Rd: Watertabling	Darkys Spur Rd: Watertabling
	

Item 6

Rural Community Board – September 2024 Photos, June-August

Dartmoor Rd: Flushing 	Dartmoor Rd: Watertabling 
Dartmoor Rd: Slip Removal 	Dartmoor Rd: Slip Removal 
Dartmoor Rd: Flooding 	Dartmoor Rd: Watertabling 

Rural Community Board – September 2024 Photos, June-August

Dartmoor Rd: Tree Removal	Dartmoor Rd: Tree Removal
	
Dartmoor Rd: Bollard Repair	Dartmoor Rd: Bollard Repair
	
Dartmoor Rd: AC Repair	Dartmoor Rd: AC Repair
	

Rural Community Board – September 2024 Photos, June-August

Duff Rd: Pautaki Low Level Bridge: Bridge Maintenance	Duff Rd: Pautaki Low Level Bridge: Sight Rail Installation
	
Ellis Wallace Rd: Tree & Slip Clearing	Ellis Wallace Rd: Tree & Slip Clearing
	
Endsleigh Rd: AC Repair	Endsleigh Rd: AC Repair
	







Rural Community Board – September 2024 Photos, June-August

Gilpin Rd: Detritus Collection		Glengarry Rd: Watertabling	
			
Glengarry Rd: Watertabling		Glengarry Rd: Scour Repair	
			
Glengarry Rd: Bund Installation		Glengarry Rd: Bund Installation	
			

Rural Community Board – September 2024 Photos, June-August

Glengarry Rd: Foliage Removal		Glengarry Rd: Watertabling & Slip Removal	
			
Glengarry Rd: Watertabling & Scour Repair		Glengarry Rd: Rock Wall Installation	
			
Glengarry Rd: Watertabling & Scour Repair		Glengarry Rd: Watertabling & Scour Repair	

Rural Community Board – September 2024 Photos, June-August







	
Glengarry Rd: Headwall Installation	Glengarry Rd: Headwall Installation
	
Glengarry Rd: Sign Pole Replacement	Glengarry Rd: Sign Pole Replacement
	
Glengarry Rd: Traffic Management	Hawkston Rd: Watertabling

Rural Community Board – September 2024 Photos, June-August



Item 6

Rural Community Board – September 2024 Photos, June-August

Hawkston Rd: Culvert Extension	Heays Access Rd: Slip Clearing
	
Heays Access Rd: Slip Clearing	Hendley Rd: Slip Removal & Dropout Bund Installation
	
Hendley Rd: Slip Removal & Dropout Bund Installation	Hendley Rd: Sign Installation
	

Item 6


Rural Community Board – September 2024 Photos, June-August

Hendley Rd: Sign Installation	Hendley Rd: Dropout Scour Repair
	
Hendley Rd: Dropout Scour Repair	Huiarangi Rd: Watertabling
	
Huiarangi Rd: Flushing	Kahika Rd: Watertabling

Rural Community Board – September 2024 Photos, June-August

	
Kahika Rd: Flushing	Kahika Rd: Clearing Slip
	
Kahika Rd: Clearing Slip	Kahuranaki Rd: Slip Clearing
	

Rural Community Board – September 2024 Photos, June-August

Kahuranaki Rd: Slip Clearing	Kahuranaki Rd: Slip Removal
	
Kahuranaki Rd: Slip Removal	Kahuranaki Rd: Slip Clearing
	
Kahuranaki Rd: Slip Clearing	Kahuranaki Rd: Slips Cleared
	
Kahuranaki Rd: Slips Cleared	Kahuranaki Rd: Tree Removal

Rural Community Board – September 2024 Photos, June-August





Item 6

Rural Community Board – September 2024 Photos, June-August

Kahuranaki Rd: Tree Removal		Kahuranaki Rd: Slip Clearing	
			
Kahuranaki Rd: Slip Clearing		Kahuranaki Rd: Slip Clearing	
			
Kahuranaki Rd: Slip Clearing		Kahuranaki Rd: Slip Clearing	
			

Item 6

Rural Community Board – September 2024 Photos, June-August

Kahuranaki Rd: Slip Clearing	Kahuranaki Rd: Sign Installation
	
Kahuranaki Rd: Sign Installation	Kaiwaka Rd: Slip Clearing
	
Kaiwaka Rd: Slip Clearing	Kereru Rd: Slip Clearing
	

Rural Community Board – September 2024 Photos, June-August

Kereru Rd: Slip Clearing	Kereru Rd: Stabilisation
	
Kereru Rd: Stabilisation	Kereru Rd: Kereru Gorge #3: Culvert Installation
	
Kereru Rd: Kereru Gorge #3: Culvert Installation	Kereru Rd: Stabilisation
	







Rural Community Board – September 2024 Photos, June-August

Kereru Rd: Stabilisation	Kereru Rd: Stabilisation
	
Kereru Rd: Stabilisation	Kereru Rd: TTM Sign Installation
	
Kereru Rd: TTM Sign Installation	Little Bush Rd: Watertabling
	


Rural Community Board – September 2024 Photos, June-August

Little Bush Rd: Culvert Maintenance	Longland Rd E: Detritus Collection
	
Longland Rd E: Detritus Collection	MacKenzie Rd: Sock Installation
	
MacKenzie Rd: Flushing	MacKenzie Rd: Limestone Headwall Installation
	

Rural Community Board – September 2024 Photos, June-August

MacKenzie Rd: Culvert Replacement	MacKenzie Rd: Soft Spot Repair
	
MacKenzie Rd: Soft Spot Repair	Makahu Rd: Headwall Installation
	
Makahu Rd: Culvert Installation	Mangatutu Rd: Tree & Slip Removal
	

Rural Community Board – September 2024 Photos, June-August

Mangatutu Rd: Tree & Slip Removal	Mangatutu Rd: Slip & Tree Removal
	
Mangatutu Rd: Slip & Tree Removal	Mangleton Rd: Hanging Branch Removal
	
Mangleton Rd: Hanging Branch Removal	Mangleton Rd: Slip Clearing
	

Rural Community Board – September 2024 Photos, June-August

Mangleton Rd: Slip Clearing	Maraekakaho Rd W: Stabilisation
	
Maraekakaho Rd W: Stabilisation	Maraetotara Rd: Dumpsite Rehabilitation
	
Maraetotara Rd: Dumpsite Rehabilitation	Maraetotara Rd: Slip Removal & Watertabling
	

Rural Community Board – September 2024 Photos, June-August

Maraetotara Rd: Slip Removal & Watertabling	Maraetotara Rd: Tomo Repair
	
Maraetotara Rd: Tomo Repair	Maraekakaho Rd W: Stabilising Rehabilitation
	
Maraekakaho Rd W: Stabilising Rehabilitation	Matahorua Rd: Slip Clearing
	

Item 6

Rural Community Board – September 2024 Photos, June-August

Matahorua Rd: Slip Clearing	Middle Rd: Detritus Collection
	
Middle Rd: Sign Installation	Middle Rd: Sign Installation
	
Middle Rd: Watertabling	Middle Rd: Watertabling
	

Rural Community Board – September 2024 Photos, June-August

Middle Rd: Stabilisation 	Middle Rd: Stabilisation 
Mokamoka Rd: Dropout Repair 	Mokamoka Rd: Dropout Repair 
Mokamoka Rd: Moka Moka Bridge: Deck Repair 	Mokamoka Rd: Moka Moka Bridge: Deck Repair 

Rural Community Board – September 2024 Photos, June-August

Mokamoka Rd: Moka Moka Bridge: Repairs	Mokamoka Rd: Moka Moka Bridge: Repairs
	
Mokamoka Rd: Safety Netting Installed	Mokamoka Rd: Safety Netting Installed
	
Moteo Pa Rd: AC Repair	Moteo Pa Rd: AC Repair
	

Rural Community Board – September 2024 Photos, June-August

Moteo Pa Rd: Detritus Collection		Mt Erin Rd: Detritus Collection	
			
Ocean Beach Rd: Old Retaining Wall Removal		Ocean Beach Rd: Old Retaining Wall Removal	
			
Ocean Beach Rd: Sight Rail Repair		Ocean Beach Rd: Sight Rail Repair	
			

Rural Community Board – September 2024 Photos, June-August

Ocean Beach Rd: Sight Rail Painting	Ocean Beach Rd: Sight Rail Painting
	
Ohiti Rd: Limestone Wall Installation	Ohiti Rd: Limestone Wall Installation
	
Ohiti Rd: Scour Repair	Ohiti Rd: Scour Repair
	

Rural Community Board – September 2024 Photos, June-August

Ohiti Rd: Scour Repair	Ohiti Rd: Scour Repair
	
Ohurakura Rd: Bollard Installation	Ohurakura Rd: Bollard Installation
	
Old Coach Rd: AC Repair	Old Coach Rd: AC Repair
	

Rural Community Board – September 2024 Photos, June-August

Old Coach Rd: AC Repair	Old Coach Rd: AC Repair
	
Old Coach Rd: Tree Removal	Old Coach Rd: Tree Removal
	
Pakaututu Rd: Culvert Unblocking	Pakaututu Rd: Culvert Unblocking
	

Rural Community Board – September 2024 Photos, June-August

Poporangi Rd: Watertabling	Poporangi Rd: Scour Repair
	
Potter Rd: Flushing	Potter Rd: Watertabling
	
Price-Cockburn Rd: Dropout Netting Installation	Price-Cockburn Rd: Dropout Netting Installation
	

Rural Community Board – September 2024 Photos, June-August

Puketapu Park: Silt & Vegetation Removal	Puketapu Park: Silt & Vegetation Removal
	
Puketitiri Rd: Bund Installation	Puketitiri Rd: Bund Installation
	
Puketitiri Rd: Watertabling & Scour Repair	Puketitiri Rd: Watertabling & Scour Repair
	

Rural Community Board – September 2024 Photos, June-August

Puketitiri Rd: Bund Installation 	Puketitiri Rd: Bund Installation 
Puketitiri Rd: Bollard & Sign Installation 	Puketitiri Rd: Bollard & Sign Installation 
Puketitiri Rd: Sign Installation 	Puketitiri Rd: Safety Netting Installation 

Rural Community Board – September 2024 Photos, June-August

Railway Rd S: Detritus Collection		Railway Rd S: Detritus Collection	
			
Raukawa Rd: Sight Rail Repair		Raukawa Rd: Sight Rail Repair	
			
Raukawa Rd: AC Repair		Raukawa Rd: AC Repair	
			

Rural Community Board – September 2024 Photos, June-August

Raukawa Rd: AC Repair	Raukawa Rd: AC Repair
	
Raukawa Rd: Culvert Installation	Raukawa Rd: Limestone Headwall Installation
	
Raukawa Rd: Detritus Collection	Ridgemount Rd: Bollard & Sign Installation
	



Rural Community Board – September 2024 Photos, June-August

Ridgemount Rd: Slip Clearing	Ridgemount Rd: Slip Clearing
	
Ridgemount Rd: Bollard & Sign Installation	Salisbury Rd: Chip Sealing
	
Salisbury Rd: Chip Sealing	Salisbury Rd: Stabilisation
	

Rural Community Board – September 2024 Photos, June-August

Salisbury Rd: Stabilisation	Seafield Rd: Detritus Collection
	
Seafield Rd: Detritus Collection	Seaview Rd: Culvert Installation
	
Seaview Rd: Culvert Installation	Stock Rd: Sight Rail Repair
	

Rural Community Board – September 2024 Photos, June-August

Stock Rd: Sight Rail Repair	Stock Rd: Oil Spill Clean Up
	
Stock Rd: Oil Spill Clean Up	Taihape Rd: Detritus Collection
	
Taihape Rd: Kawera Bridge: Bridge Maintenance	Taihape Rd: Kawera Bridge: Bridge Maintenance
	

Rural Community Board – September 2024 Photos, June-August

Taihape Rd: Kawera Bridge: Sight Rail Installation	Taihape Rd: Kawera Bridge: Sign Installation
	
Taihape Rd: Sign Installation	Taihape Rd: Sign Installation
	
Taihape Rd: Fallen Tree Removal	Taihape Rd: Fallen Tree Removal
	

Rural Community Board – September 2024 Photos, June-August

Taihape Rd: Slip Removal	Taihape Rd: Slip Removal
	
Taihape Rd: Slip Clearing	Taihape Rd: Slip Clearing
	
Taihape Rd: Limesand Footpath Repair	Taihape Rd: Limesand Footpath Repair
	

Rural Community Board – September 2024 Photos, June-August

Taihape Rd: Slip Clearing		Taihape Rd: Slip Clearing	
			
Taihape Rd: Sealing		Taihape Rd: Sealing	
			
Taihape Rd: Sign Installation		Tangoio Settlement Rd: Slips Clearing	
			

Rural Community Board – September 2024 Photos, June-August

Tangoio Settlement Rd: Slips Clearing	Tareha Rd: Scour Repair
	
Tareha Rd: Scour Repair	Te Apiti Rd N: Mud Debris Removal
	
Te Apiti Rd N: Mud Debris Removal	Tuki Tuki Rd: Watertabling
	





Rural Community Board – September 2024 Photos, June-August

Tuki Tuki Rd: Watertabling	Turangakumu Rd: Illegal Lock Removal
	
Turangakumu Rd: Illegal Lock Removal	Turangakumu Rd: Illegal Gate Removal
	
Turangakumu Rd: Illegal Gate Removal	Valley Rd: Stabilisation
	

Rural Community Board – September 2024 Photos, June-August

Valley Rd: Stabilisation	Waihau Rd: Horgans Bridge: Inspection
	
Waihau Rd: Horgans Bridge: Inspection	Waihau Rd: Horgans Bridge: Scour Repair
	
Waihau Rd: Horgans Bridge: Scour Repair	Waihau Rd: Horgans Bridge: Final Inspection

Rural Community Board – September 2024 Photos, June-August

	
Waihau Rd: Horgans Bridge: Final Inspection	Waihau Rd: Dropout Barrier Repair
	
Waihau Rd: Dropout Barrier Repair	Waihau Rd: Averys Bridge: Sign Installation
	
Waihau Rd: Averys Bridge: Bollard Installation	Waihau Rd: Slip Clearing

Rural Community Board – September 2024 Photos, June-August




Item 6




Rural Community Board – September 2024 Photos, June-August

Waihau Rd: Slip Clearing	Waikare Rd: Slip Clearing
	
Waikare Rd: Slip Clearing	Waikare Rd: Slip Clearing
	
Waikare Rd: Slip Clearing	Waikoa Rd: Waikoa Gorge Bridge: Prep Work
	

Rural Community Board – September 2024 Photos, June-August

Waikoau Rd: Waikoau Gorge Bridge: Prep Work	Waikoau Rd: Waikoau Gorge Bridge: Hydro Blasting
	
Waikoau Rd: Waikoau Gorge Bridge: Hydro Blasting	Waikoau Rd: Waikoau Gorge Bridge: Strengthening Project
	
Waikoau Rd: Waikoau Gorge Bridge: Strengthening Project	Waikoau Rd: Waikoau Gorge Bridge: Strengthening Project
	

Rural Community Board – September 2024 Photos, June-August

Waikoau Rd: Waikoau Gorge Bridge: Speed Bump Installation	Waikoau Rd: Waikoau Gorge Bridge: Strengthening Project
	
Waikoau Rd: Waikoau Gorge Bridge: Strengthening Project	Waikoau Rd: Waikoau Gorge Bridge: Strengthening Project
	
Waikoau Rd: Waikoau Gorge Bridge: Strengthening Project	Waikoau Rd: Waikoau Gorge Bridge: Speed Bump Installation
	

Rural Community Board – September 2024 Photos, June-August

Waikoau Rd: Waikoau Gorge Bridge: Speed Bump Installation		Waikoau Rd: Waikoau Gorge Bridge: Strengthening Project	
			
Waikoau Rd: Tree Removal		Waikoau Rd: Tree Removal	
			
Waikoau Rd: Waikoau Gorge Bridge: Strengthening Project		Waikoau Rd: Waikoau Gorge Bridge: Strengthening Project	
			

Rural Community Board – September 2024 Photos, June-August

Waikoau Rd: Waikoau Gorge Bridge: Strengthening Project



Waikoau Rd: Waikoau Gorge Bridge: Scaffolding Installation



Waikoau Rd: Waikoau Gorge Bridge: Scaffolding Installation



Waikoau Rd: Waikoau Gorge Bridge: Scaffolding Installation



Waikoau Rd: Waikoau Gorge Bridge: Scaffolding Installation



Waikoau Rd: Dropout Repair



Rural Community Board – September 2024 Photos, June-August

Waikoau Rd: Dropout Repair	Waikoau Rd: Clearing Slip
	
Waikoau Rd: Clearing Slip	Waikoau Rd: Waikoau Gorge Bridge: Scaffold Removal
	
Waikoau Rd: Waikoau Gorge Bridge: Scaffold Removal	Waimarama Rd: Red Bridge: Clear Water Channels
	

Rural Community Board – September 2024 Photos, June-August

Waimarama Rd: Red Bridge: Clear Water Channels	Waimarama Rd: Sign Replacement
	
Waimarama Rd: Sign Replacement	Waimarama Rd: Sign Replacement
	
Waimarama Rd: Sign Replacement	Waimarama Rd: Detritus Collection
	

Rural Community Board – September 2024 Photos, June-August

Waimarama Rd: Slip Clearing 	Waimarama Rd: Slip Clearing 
Waimarama Rd: Slip Clearing 	Waimarama Rd: Slip Clearing 
Waimarama Rd: Red Bridge: Clear Water Channels 	Waimarama Rd: Red Bridge: Clear Water Channels 

Rural Community Board – September 2024 Photos, June-August

Waiohiki Rd: Sign Installation	Waiohiki Rd: Sign Installation
	
Waipatiki Rd: Dropout Repair	Waipatiki Rd: Dropout Repair
	
Waipunga Rd: Slip Clearing	Waipunga Rd: Slip Clearing
	

Rural Community Board – September 2024 Photos, June-August

Waipunga Rd: Slip Cleared		Waipunga Rd: Slip Cleared	
			
Waipunga Rd: Clearing Slips		Waipunga Rd: Clearing Slips	
			
Waipunga Rd: Dropout Repair		Waipunga Rd: Dropout Repair	
			

Item 6

Rural Community Board – September 2024 Photos, June-August

Waitangi Rd: Watertabling	Waitangi Rd: Watertabling
	
Waitara Rd: Watertabling & Slip Cleared	Waitara Rd: Scour Repair & Headwall Installation
	
Waitara Rd: Watertabling	Waitara Rd: Scour Repair
	

Rural Community Board – September 2024 Photos, June-August

Waitara Rd: Slip Clearing, Watertabling & Scour Repair	Waitara Rd: Lime Rock Headwall Installation
	
Waitara Rd: Culvert & Headwall Installation	Waitara Rd: Sock Installation
	
Waitara Rd: Scour Repair & Sock Installation	Waitara Rd: Scour Repair & Sock Installation
	

Rural Community Board – September 2024 Photos, June-August

Waitara Rd: Rock Wall Installation	
	
Waitara Rd: Slip Clearing	
	
Whanawhana Rd: Whanawhana Bridge: Sight Rail Repair	
	

Rural Community Board – September 2024 Photos, June-August