

Monday, 15 December 2025

*Te Hui o Te Kaunihera ā-Rohe o Heretaunga*

**Hastings District Council**

**Hastings District Rural Community Board Meeting**

*Kaupapataka*

# Attachments

---

*Te Rā Hui:*  
Meeting date: **Monday, 15 December 2025**

---

*Te Wā:*  
Time: **1:00 PM**

---

*Te Wāhi:*  
Venue: **Council Chamber  
Ground Floor  
Civic Administration Building  
Lyndon Road East  
Hastings**

---

**Watch Council meetings  
streamed live on our website  
[www.hastingsdc.govt.nz](http://www.hastingsdc.govt.nz)**

**HASTINGS DISTRICT COUNCIL**  
207 Lyndon Road East, Hastings 4122 | Private Bag 9002, Hastings 4156  
Phone **06 871 5000** | [www.hastingsdc.govt.nz](http://www.hastingsdc.govt.nz)  
**TE KAUNIHERA Ā-ROHE O HERETAUNGA**

ITEM	SUBJECT	PAGE
6.	<b>RURAL TRANSPORTATION ACTIVITY REPORT</b>	
	Attachment 1: RCB Photos - August - Nov 2025	3



<i>Apley – High Shoulder</i> 	<i>Apley – High Shoulder</i> 
<i>Apley Rd – Preseal Repairs</i> 	<i>Apley Rd – Preseal Repairs</i> 
<i>Bridge 308 Fields – Removed stock fence</i> 	<i>Bridge 308 Fields – Removed stock fence</i> 



B# 312 Lambs Hill No 1- Maintenance	
	
Bridge Pa - Callout	
	
Burma Rd - Grading	
	

<i>Dartmoor Rd – Sign replacement</i>	<i>Dartmoor Rd – Sign replacement</i>
	
<i>Dartmoor Rd – Sign repair</i>	<i>Dartmoor Rd – Sign repair</i>
	
<i>Ellis Wallace – Bridge maintenance</i>	<i>Ellis Wallace – Bridge maintenance</i>
	



<i>Endsleigh Rd - Potholes</i>	<i>Endsleigh Rd - Potholes</i>
	
<i>Endsleigh Rd – Scour repair</i>	<i>Endsleigh Rd – Scour repair</i>
	
<i>Flat Hill Rd – Culvert inspection</i>	<i>Flat Hill Rd – Culvert inspection</i>
	

<i>Glenross Rd - Tree</i> 	<i>Glenross Rd - Tree</i> 
<i>Horonui Rd - Bridge Maintenance</i> 	<i>Horonui Rd - Bridge Maintenance</i> 
<i>Kahika Rd - Grading</i> 	<i>Kahika Rd - Grading</i> 

Rural Community Board – December 2025 Meeting – Photos August to November



<i>Kahuranaki Rd – Drainage work</i>	<i>Kahuranaki Rd – Drainage work</i>
	
<i>Kereru Rd - Potholes</i>	<i>Kereru Rd - Potholes</i>
	
<i>Longlands Rd – Edgebreak</i>	<i>Longlands Rd – Edgebreak</i>
	



<i>Matahorua Rd – Downed tree/powerlines</i>	<i>Matahorua Rd – Downed tree/powerlines</i>
	
<i>Matahorua Rd – Culvert inspections</i>	<i>Matahorua Rd – Culvert inspections</i>
	
<i>Matahorua – Scour repair</i>	<i>Matahorua – Scour repair</i>
	

<i>Matahorua – Scour repair</i>	<i>Matahorua – Scour repair</i>
	
<i>Ngatarawa Rd - Litter</i>	<i>Ngatarawa Rd - Litter</i>
	
<i>Ocean Beach Rd – Sign replacement</i>	<i>Ocean Beach Rd – Sign replacement</i>
	

Rural Community Board – December 2025 Meeting – Photos August to November



<i>Ohuakura Rd – Bridge maintenance</i> 	<i>Ohuakura Rd – Bridge maintenance</i> 
<i>Pakaututu Rd - Grading</i> 	<i>Pakaututu Rd - Grading</i> 
<i>Pirau Rd - Grading</i> 	<i>Pirau Rd - Grading</i> 

Rural Community Board – December 2025 Meeting – Photos August to November



<p>Pohokura Rd -Tree</p> 	<p>Pohokura Rd -Tree</p> 
<p>Puketapu Domain - Kerbing</p> 	<p>Puketapu Domain - Kerbing</p> 
<p>Puketitiri Rd - Potholes</p> 	<p>Puketitiri Rd - Potholes</p> 

Rural Community Board – December 2025 Meeting – Photos August to November









<i>Puketitiri Rd -Signs</i>	<i>Puketitiri Rd -Signs</i>
	
<i>Puketitiri Rd – Bridge Maint.</i>	<i>Puketitiri Rd – Bridge Maint.</i>
	
<i>Raukawa Rd - Tree</i>	<i>Raukawa Rd - Tree</i>
	

Rural Community Board – December 2025 Meeting – Photos August to November



<i>Reds Bridge – Bridge Maintenance</i>	<i>Reds Bridge – Bridge Maintenance</i>
	
<i>Riggers Bridge – Post replacement</i>	<i>Riggers Bridge – Post replacement</i>
	
<i>Salisbury Rd – Drainage install</i>	<i>Salisbury Rd – Drainage install</i>
	

Rural Community Board – December 2025 Meeting – Photos August to November

<i>Soldier Settlement – Tree</i> 	<i>Soldier Settlement - Tree</i> 
<i>Swamp rd – Sight Rails</i> 	<i>Swamp rd – Sight Rails</i> 
<i>Taheke Rd - Stabilising</i> 	<i>Taheke Rd - Stabilising</i> 

  
355\_Weekly  
Report\_WE05102025



<i>Taihape Rd – Scour repair</i>	<i>Taihape Rd – Scour repair</i>
	
<i>Taihape Rd – Footpath drainage</i>	<i>Taihape Rd – Footpath drainage</i>
	
<i>Taihape Rd – Pothole repairs</i>	<i>Taihape Rd – Pothole repairs</i>
	






Taihape Rd – Test Pits		Taihape Rd – Test Pits	
			
Taihape rd - Callout		Taihape rd - Callout	
			
Taihape Rd – Sign Maint.		Taihape Rd – Sign Maint.	
			

<i>Tait Rd – Silt clearing</i>		<i>Tait Rd – Silt clearing</i>	
<i>Tangoio Settlement - Metalling</i>		<i>Tangoio Settlement - Metalling</i>	
<i>Tangoio Settlement – sign conditioning</i>		<i>Tangoio Settlement – sign conditioning</i>	



Tangoio Settlement - Watertable		Tangoio Settlement - Watertable	
			
Tawa Rd – Culvert install		Tawa Rd – Culvert install	
			
Waikoau Rd – Unsealed maintenance		Waikoau Rd – Unsealed maintenance	
			



<p>Waimarama Domain – Fallen Tree</p> 	<p>Waimarama Domain – Fallen Tree</p> 
<p>Waipunga Rd – Unsealed Pavement Repair</p> 	<p>Waipunga Rd – Unsealed Pavement Repair</p> 